

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors ors
1	IS&R	L1	1760	USPAT; EPO; JPO; DERWEN	2001/09/29 04:34	T	0	
2	IS&R	L2	1771 (("378/4") or ("378/19") or EPO; ("378/20")).CCLS.	USPAT; UB; US-PGP	2001/09/29 04:34	JPO; DERWEN	0	
3	B.P.S	L3	452 2 and gantry	USPAT; EPO; JPO;	2001/09/29	DERWEN	0	
4	B.P.S	L4	387 3 and source	USPAT; EPO; JPO; DERWEN	2001/09/29 04:34	T	0	
5	B.P.S	L5	372 4 and table	USPAT; EPO; JPO;	2001/09/29 04:34	DERWEN	0	
6	E.P.S	L6	5 and (flavor and stand)	USPAT; EPO; JPO;	2001/09/29 04:35	DERWEN	0	

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
7	BRS	L7	24 5 and floor	USPAT; EPO; JPO; DERWEN T	2001/09/29 04:35			0
8	BRS	L9	6 8 and moveable	USPAT; EPO; JPO; DERWEN T	2001/09/29 04:35			0
9	BRS	L10	5 6	USPAT; EPO; JPO; DERWEN T	2001/09/29 04:35			0
10	BRS	L8	7 and ceiling	USPAT; EPO; JPO; DERWEN T	2001/09/29 05:24			0
11	BRS	L11	14 computed tomography	USPAT; EPO; JPO; DERWEN T	2001/09/29 05:24			0
12	BRS	L12	15 implemented adj tomography	USPAT; EPO; JPO; DERWEN T	2001/09/29 05:24			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
13	BRS	L13	40 12 and ceiling	USPAT; EPO; JPO; DERWEN T	2001/09/29 05:24	0		
14	BRS	L14	"40" and (ceiling same table)	USPAT; EPO; JPO; DERWEN T	2001/09/29 05:25	0		
15	BRS	L15	14 and (ceiling same table)	USPAT; EPO; JPO; DERWEN T	2001/09/29 05:25	0		
16	BRS	L16	13 and (ceiling same table)	USPAT; EPO; JPO; DERWEN T	2001/09/29 05:25	0		